



## JACKSONVILLE HOOD CLEANING LLC

8787 SOUTHSIDE BLVD APT 6308  
 JACKSONVILLE, FL, 32256  
 www.jacksonvillehoodcleaning.com  
 jacksonvillehoodcleaning@gmail.com  
 Cel.: (904) 607 4724 Fax: (904) 551 1539

## REPORT

Number Invoice: 99  
 Number Service: 99  
 Date Invoice: 10/09/2014  
 Date Service: 07/01/2013

Business Name		
EXAMPLE		
Address	City	State
XXX XXXXXXXXXXXXXXXXX	JACKSONVILLE	Florida
Zip Code	Phone	Fax
32256	904-111-1111	904-111-1111

### SYSTEMS INFORMATIONS

System	Size hood	frequency of cleaning	Filters number	Number access	Number fans
FRYER AND GRIDDLE	12	1	6	0	1
RANGE AND BURNER	12	1	6	0	1
PIT BBQ	5	1	6	0	1

### PRE CLEANING CHECKS

	FRYER AND GRIDDLE	RANGE AND BURNER	PIT BBQ
Filter missing or damaged	No	No	No
Exhaust fan operational	Yes	Yes	No
Hinge kits needed for exhaust fan	No	No	No
Bare wires /exposed wires / wires too short	No	No	No
Missing or damaged canopy hood lights	No	No	No
Hood lights operational	Yes	Yes	Yes
Fan Dented or damaged	No	No	No
Grease accumulation on roof surface	Yes	Yes	No
Overall grease condition of system	Yes	Yes	Yes
Additional access panels required	No	No	No
Missing fan grease catcher box	No	Yes	No
Missing hood grease cups	No	No	No
Other	No	Yes	No

### SERVICES PERFORMED

	FRYER AND GRIDDLE	RANGE AND BURNER	PIT BBQ
Vertical duct cleaned	Yes	Yes	Yes
Horizontal duct cleaned	Yes	Yes	No
Exhaust fan cleaned	Yes	Yes	No
fan belts inspected	Yes	Yes	No
Additional cleaned performed	No	Yes	No
Access panels opened	No	No	No
Filters cleaned	Yes	Yes	No
Canopy hood lights cleaned	Yes	Yes	No

## POST CLEANING CHECKS

	FRYER AND GRIDDLE	RANGE AND BURNER	PIT BBQ
Exhaust system leaks	No	No	No
Exhaust fan restarted	Yes	Yes	No
Pilot lights reignited	Yes	Yes	Yes
Roof area near fan rinsed off	Yes	Yes	Yes
Floor mopped	Yes	Yes	Yes
Hood wiped dry and polish	Yes	Yes	No
Grease containers located in position	Yes	Yes	No
Filters located in position	Yes	Yes	No
Hood sticker replaced	Yes	Yes	Yes

### Notes/Coments

---

All cleaning is in accordance with local fire codes and/or NFPA code # 96. This courtesy follow-up report is provided as a free customer service only, it is not a paid consultation.  
The inspection of the exhaust system is limited to the possible need for improved access and cleaning only. Other deficiencies, whether reported or not, are beyond the scope of our cleaning crew's knowledge. It is the exhaust system's responsibility to take appropriate action to modify any deficiencies noted herein or elsewhere.  
I hereby acknowledge the satisfactory completion of the above described work. I understand this constitute notification of any work, not performed area not cleaned and/or any deficiencies in the exhaust systems as noted