



# JACKSONVILLE HOOD CLEANING LLC

8787 SOUTHSIDE BLVD APT 6308  
 JACKSONVILLE, FL, 32256  
 www.jacksonvillehoodcleaning.com  
 jacksonvillehoodcleaning@gmail.com  
 Cel.: (904) 607 4724 Fax: (904) 551 1539

# PHOTOS

Number Invoice: 99  
 Number Service: 99  
 Date Invoice: 10/09/2014  
 Date Service: 07/01/2013



Business Name		
EXAMPLE		
Address	City	State
XXX XXXXXXXXXXXXXXXXX	JACKSONVILLE	Florida
Zip Code	Phone	Fax
32256	904-111-1111	904-111-1111









## SYSTEMS INFORMATIONS

System	Size hood	frequency of cleaning	Filters number	Number access	Number fans
FRYER AND GRIDDLE	12	1	6	0	1
RANGE AND BURNER	12	1	6	0	1
PIT BBQ	5	1	6	0	1


FRYER AND GRIDDLE	BEFORE	AFTER
FAN		
FAN		

DUCT



RANGE AND BURNER	BEFORE	AFTER
FAN		
FAN		
DUCT		
GREASE REMOVAL FROM ROOF		

NEW GREASE  
TRAP



PIT BBQ	BEFORE	AFTER
	 A dark, unlit interior of a pit BBQ. A metal grate is visible at the bottom. The walls are made of brick or stone, and the lighting is very dim, highlighting the texture of the masonry.	 The interior of the pit BBQ is now well-lit. The walls are made of light-colored brick or stone. A metal grate is visible at the bottom. The lighting is bright and even, showing the details of the masonry.
	 A close-up view of the interior of a pit BBQ. A metal grate is visible at the bottom. The walls are made of brick or stone, and the lighting is very dim, highlighting the texture of the masonry.	 A close-up view of the interior of a pit BBQ. A metal grate is visible at the bottom. The walls are made of light-colored brick or stone. The lighting is bright and even, showing the details of the masonry.